Cable checking - email@glasmacher-electronic.de


Measuring Head pi


Where is the cable problem? Where is the cable loose?

A 1 1 1 1 1 1 1 1 1 1

Measuring device

TGM






Cable checking - email@glasmacher-electronic.de

Open the measuring device

- Check the terminal block: if you pushing the white lever down the cable is loose – please use ferrules or tin the stripped cable
- Check the cable grommet often the glue gets loose we recommend a special glue for TPE (for example Loctite)

PLEASE DISCONNECT THE BATTERY IMMEDIATLY AFTER OPENING

Cable checking - email@glasmacher-electronic.de




Because of repeated problems with the cable grommmet we changed it in early 2018 from glueing to clamping – please contact <u>email@glasmacher-electronic.de</u> so we can change for you in Germany or send you the metall clamp free of charge so you can change



email@glasmacher-electronic.de 🕓 0049 178 1458802

- Remove the old rubber cable entry
- Widen the hole to 7mm diameter with a drill or file
- Insert the wider new rubber cable entry







After removal of the old one widen the bigger hole to 7mm



email@glasmacher-electronic.de S 0049 178 1458802


1. Insert the end without the cable ties from the inside of the sensor case through the rubber cable entry. Put a little water on the cable so it goes easy through the rubber cable entry









email@glasmacher-electronic.de 0049 178 1458802 2. Pull the cable all the way through the rubber cable entry (with a little water it goes easier) till the cable tie sits directly before the rubber cable entry








email@glasmacher-electronic.de S 0049 178 1458802 2. Pull the cable all the way through the rubber cable entry (with a little water it goes easier) till the cable tie sits directly before the rubber cable entry



Put the 4 loose ends without the cable tie through the metall cable entry



Open the metall cable entry and put the outter part with the rubber a bit over the isolated black part of the cable





Pull the cable through the metall clamp till about 1cm is out of the unisolated cable – reconnect the metall clamp – a bit of water on the cable makes it easier



email@glasmacher-electronic.de 🕓 0049 178 1458802

- Put the bigger shrink tubing over the loose ends on the side of the metall clamp
- The shrink tubing should sit half over the 4 loose cables and half over the unisolated black cable
- Shrink it with heat
- Pull the cable slightly back so the shrinked part sits just in front of the metall clamp
- Tighten the metall clamp





2W2 2328


Replace the cable entry

Remove or sand down the two little plastic noses



email@glasmacher-electronic.de 0049 178 1458802

> To be soldered to the cutted cables in the sensor case



SOUL FTA FOR A CT



To be clamped in the PCB terminal in the handheld TGM