

doorclosingmeter.com glasmacher electronic GmbH



- •Screw the threaded stays in the M 5 Side of the adapter
- •Screw for example the goose neck on the threaded stays
- •Tighten with the hexagon socket of the threded stays



doorclosingmeter.com glasmacher electronic GmbH

Tripod Adapter

to mount the TGM measuring Head on a photo tripod

- •¼" −20 UNC *Tripod Side*
- •M 5 TGM Side

M 5 Threaded Stays Goose Neck

